

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Update of flash firmware version to V2.3 affecting dedicated products of the AURIX product family.

N° 043/16

Update of flash firmware version to V2.3 affecting dedicated products of the AURIX product family.

► Products affected:

Please refer to 1_cip04316_update attached.

Please note that 3 products have been excluded from the change. These products are marked in the attachment.

► Detailed Change Information:

Subject: Update of flash firmware version to V2.3 affecting dedicated products of the AURIX product family (flash firmware change).

Reason: Weakness of the erase suspend function of the data flash for devices with flash firmware version \leq V2.2 (for details please refer to FLASH_TC_044_EPN_v1_1_03625A EPN from August 7, 2015 attached).

Description:	<u>Old</u>	<u>New</u>
flash firmware version:	■ \leq V2.2	■ V2.3 (for details please refer to FLASH_TC_044_EPN_v1_1_03625A from August 7, 2015 attached).

► Attachments:

1_cip04316_update: affected product list

4_cip04316: FLASH_TC_044_EPN_v1_1_03625A

► Intended start of delivery:

Since Q1/2016

If you have any questions, please do not hesitate to contact your local Sales office.